



DEPARTMENT OF THE ARMY
U.S. ARMY COMBAT CAPABILITIES DEVELOPMENT COMMAND
AVIATION AND MISSILE CENTER
5400 FOWLER ROAD
REDSTONE ARSENAL, ALABAMA 35898

System Readiness Directorate

Mr. Paul Bolton
Technical Director
Aviation Blade Services
3969 Merlin Drive
Kissimmee, Florida 34741

Dear Mr. Bolton:

The System Readiness Directorate completed the review of your Maintenance and Overhaul (M&O) Source Approval Request (SAR) Z09-001-19. I am pleased to inform you that Aviation Blades Services, Incorporated, CAGE Code 1EKF5, was added as an approved source for the UH-60 Main Rotor Blade Assembly (repair levels 1-3 only), Part Number 70150-09100-043, National Stock Number 1615-01-106-1903. This approval is based on the technical capabilities provided in your SAR package to perform M&O of the aforementioned component. This approval is for M&O only and is not to be considered an approval to manufacture replacement parts. Manufacturing of replacement parts is covered under the Spares program and will be handled separately.

Should Aviation Blades Services, Incorporated be awarded a M&O contract for the aforementioned component, updated planning, which includes the current revision of the Depot Maintenance Work Requirement and applicable Maintenance Engineering Orders, may be required in accordance with contractual requirements.

The point of contact for this action is Mr. Lee Drake, Aviation Sustainment Branch, Quality Engineering Division, 256-313-6371, or E-mail: lee.c.drake.civ@mail.mil. The alternate point of contact is Mr. Tim Hampton, Aviation Sustainment Branch, Quality Engineering Division, 256-876-3198, or E-mail: timothy.o.hampton.civ@mail.mil.

Sincerely,

BRUCE SANDS
Acting Associate Director, Product Assurance
for Materiel Suitability
Systems Readiness Directorate